

UNITED STATES ENVIRONMENTAL PROTECTION AGENCY SUPERFUND SITE STRATEGY RECOMMENDATION - REGION 06



Site Name: Section 19 Mine - NM0036	CERCLIS ID#: N/A	
Alias Site Name: Section 20	***	
Address: Latitude 35 degrees 26'19.11" Longitu	ide 107 degrees 49'10.52"	
City/County or Parish/State/Zip: McKinley	County, New Mexico	
Report Type: Pre-CERCLIS Screening	Date: 10/31/11	Author: NMED
	•	
RECOMMENDATION:		
1. No Further Remedial Action Planned Under Superfund (NFRAP)	☐ PA ☐ SI ☐ ES ☐ Otl	RI/FS Low I RA ner:
		performed by:
3. Action Deferred to: RCRA NF 4. Site Being Addressed Under the State Vo		(VCP): Yes No
NOTIFY AUTHORITY:	•	
☐ Removal ☐ RCRA ☐ TSO ☐ Remedial ☐ State/Tribe ☐ NPI ☐ CERCLA ☐ Federal ☐ UIO	DES 🔲 NRC	SMCRA Resource Trustee: Other:
Enforcement Facility	, _	``
SEND SSSR COPIES TO: 6SF-AC [☐ 6WQ-SP ☐ ATS	DR State Agency Tribal Agency
DISCUSSION:		
The New Mexico Environment Department (NM Section 19 Mine site. The mine operated as a w occurred (i.e., mine water was recirculated throu are located on Section 19 and the underground v	et mine and records indicated the mine to further lead	te that during mine operations, solution mining h uranium). The surface facilities and main shaf
Mine reclamation is being required pursuant to t discharge of mine water and solution mining is t Commission regulations.		
NMED recommended that no further action be t activities pursuant to New Mexico regulations.		

Page 1 of 2

APPROVALS:	·		<u> </u>	
Report Reviewed by:	Lisa Marie Price (Site Assessment Manager)	Signature:	hallan fra	Date: 4/29/1/
 Disposition Approved by:	John Meyer (Section Chief 6SF-TR)	Signature:	John Neys	Date: 1/29/11